

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-016188**Date Inspected:** 07-Aug-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai,China

CWI Name:	N/A	CWI Present:	Yes	No
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use: Yes No N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed: Yes No N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up: Yes No N/A
Approved Drawings:	Yes	No	N/A	Approved WPS: Yes No N/A
				Delayed / Cancelled: Yes No N/A
Bridge No:	34-0006	Component:	OBG	

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Nagalingam Pandaram Pillai was present during the times noted above for observations relative to the work being performed.

Magnetic Particle Testing:-

Out Side Yard

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control Personnel. This QA Inspector generated an MT report for this date. The member is identified as OBG Segment 11EW. The weld designation reviewed is as follows:

DP134-002-009 TO 046
DP161-001-011 TO 057
DP188-001-011 TO 057
DP215-001-011 TO 057
SSD13A-PP107-125,126.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

No Relevant Conversation.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By: Pillai,Pandaram

Quality Assurance Inspector

Reviewed By: McClendon,Timothy

QA Reviewer